

Figure 1: Ex. Playground Pod



Figure 2: Ex. Swings



Figure 3: Ex. Concrete Area



Figure 4: Ex. Concrete Playground Curb Edging




Figures 5: Ex. Seating Area



Figures 6: Ex. Bike Rack


Site Analysis


- Concrete curb in good condition
- Play surface is sand. No reported flooding in pod.
- Playground pod includes multiple metal climbing structures, slides, seperate swings, and balance beams.
- Playground pod bordered by berms and mature trees
- Light poles located around the perimeter of the playground pod. Electrical line most likely in alignment with the edge of the concrete curb.
- Sightlines into and out of the play areas are good



Project Vision

 Existing playground pod layout, size, and curbing to remain







- Existing light pole to be retained
- All existing site furniture including benches, picnic table, and bike racks will be replaced with new furniture
- Existing cracks within the concrete surfaces will be repaired

*Play elements shown are

chosen may differ based on

public feedback, budget and

City policies.

examples only. Actual elements




Swinging Play Element



Sliding Play Element





Rotating Play Element



Hanging Play Element



Balance Play Element

Meyonohk Park Playground Renewal

Meyonohk Neighbourhood - 1840 Lakewood Rd S NW