

**Conditions Legend** 

Biogrowth
Crack

Pipe End


Ferrous Staining

**Concrete Deterioration** 

**Metal Deterioration** 

The Conditions Legend is specific to the subject

building of each report and conditions drawing set.



CHAIN LINK FENCE

PLYWOOD

OPEN TO BELOW

MASKED REGION

PROJECTING SURFACE

CUT SURFACE

## Consultant

the marc boutin architectural collaborative inc. 205 9th Avenue SE, Suite 100 Calgary, AB, T2G 0R3

MECHANICAL/ELECTRICAL
Williams Engineering Canada Inc.
10065 Jasper Ave #200,
Edmonton, AB T5J 3B1
Contact: Sheldon Samborsky (M), Ben Ra

MECHANICAL/ELECTRICAL

DFS Inc Architecture & Design 400 Boulevard de Maisonneuve O, Montréal, QC H3A 1L4 Contact: Evan Oxland ARCHITECTURAL

BUILDING/FIRE CODE Jensen Hughes 5855 9 St SE #106, Calgary, AB T2H 1Z9 Contact: Kyle Duckworth COST BTY Group 404 6 Ave SW #645, Calgary, AB T2P 0R9 Contact: Michael Gabert

Saucier + Perrotte Architectes 7043 Waverly St, Montreal, QC H2S 3J1 Contact: Anne-Marie Saucier STRUCTURAL/CIVIL/BUILDING ENVELOPE Read Jones Christoffersen Ltd 17415 102 Ave NW #100, Edmonton, AB T5S 1J8

Naheyawin 1205 - 10903 103 Ave NW, Edmonton, Alberta, T5K 2X6

Contact: Frank Cavaliere (S), John Balla (C), Nick Trovato (BE) CONSULTANT PROJECT 20008

PRELIMINARY NOT FOR CONSTRUCTION



ROSSDALE POWER PLANT ADVANCED ASSESSMENT AND PRIORITY REHABILITATION -HISTORIC BUILDING RECORD

CP-9496

Department INTEGRATED INFRASTRUCTURE SERVICES

No.	Description	Date					
1	Conditions Assessment Revision 1						
2	Conditions Assessment Revision 2						
3	Conditions Assessment Revision 3						
4	Conditions Assessment Revision 4	03/09/2021					
5	Conditions Assessment Revision 5						

Location ID ROS112

ATCO GAS BUILDING -CONDITIONS ASSESSMENT

ATCO FLOOR PLANS

	Discipline	HERITAGE	Drawn	B.H.
	Volume		Drawing	
	Sheet	H250	Drawing Number	
	File			