



# NORTHWEST LRT - 132 AVENUE STATION



Tracks located between adjacent houses

Shared use path

Increased accessibility for both nearby schools and activity centres

Easy Bus exchange

No property Impact

Pedestrian and cyclist access and facilities

Property Impact

Access closed

Enhanced shared use path connection

Property Impact

Landscaping and fenced from dog park

Minimizes impact to park

Reduced traffic south of 137 Avenue

Retained on-street parking

Property Impact

Pedestrian crossings provided

Property Impact

Retained traffic access

Pedestrian crossings provided

Property Impact

New pedestrian and cyclist connection to downtown

**TRANSIT ORIENTED DEVELOPMENT (TOD)**  
 At station locations, City policy supports transit oriented development, as specified in the TOD Guidelines or determined through a station area planning process.

**LEGEND**

LRT at Grade	Bus Stop	LRT Equipment Room
Underground LRT	Signal Intersection	Trees / Planting
Elevated LRT	Directional Arrows	Bicycle Parking
LRT Station	Pavement Markings	
Roadworks	Fence	
Shared Use Path	Access Closed	
Sidewalk	Pedestrian Crossing	
On-Street Parking		
Property Required		